

LXM26

			LXM26		
10	P+		41	PULSE	1
11	P-		43	/PULSE	
13	S+		37	SIGN	2
14	S-		36	/SIGN	
2	A+	A	21	0A	A
3	A-		22	/0A	
4	B+	B	25	0B	B
5	B-		23	/0B	
6	Z+	Z	50	0Z	C
7	Z-		24	/0Z	
1	+24V	+24V	11	COM+	DC24V +
9	0V	24V	45	COM-	DC24V -
			6	ALRM-	45
			26	D04-	45
15	ALRM		7	ALRM+ (DO	
8	SON		9	SON	
0V			1	D04+	

P1-00		1
P1-01		
P1-44		128
P1-45		1
P2-10		101
P2-18		101
P2-21		108
		0
		0
		0