

AB

			ASDA-B2					
						P1-00		1
						P1-01		0 100
10	P+		43	PULSE	1	P1-03		0 10
11	P-		41	/PULSE		P2-10		101 001
13	S+		36	SIGN	2	P1-44		16
14	S-		37	/SIGN		P1-45		1
2	A+	A	21	OA		P2-21		108
3	A-		22	/OA		P2-15		0
4	B+	B	25	OB	B	P2-16		0
5	B-		23	/OB		P2-17		0
6	Z+	Z	50	OZ	C	P1-46		12500
7	Z-		24	/OZ				
1	+24V	+24V	11	COM+	DC24V	+		
9	0V	24V	45 47 49 27 26	COM-	DC24V	-		
			27	ALRM-	45 (COM-)			
15	ALRM		28	ALRM+				
8	SON		9	SON				
12	BARKE		1	D04+				
			26	D04-	45 (COM-)			