

			A6					
						Pr0.00		0 1
10	P+		3	PULSH	1	Pr0.01		0
11	P-		4	PULSH		Pr0.05		0
13	S+		5	SIGNH	2	Pr0.06		0
14	S-		6	SIGNH		Pr0.07		1
2	A+	A	21	OA+	A	Pr0.08		10000
3	A-		22	OA-		Pr0.11		2500
4	B+	B	48	OB+	B	Pr0.12		0 1
5	B-		49	OB-				
6	Z+	Z	23	OZ+	Z			
7	Z-		24	OZ-				
1	+24V	+24V	7	COM+	+			
9	GND	+24V	41	COM-	-			
8	SON		29	SRV-ON				
15	ALRM		37	ALM+				
			36	ALM-	41 COM-			
12	BRAKE		11	BRKOFF+				
			10	BRKOFF-	41 COM-			